

**APPENDIX G**

**VARIANCE REPORTS**



Variance No: MP3100DEC.VAR

Linked w/NC No:

X

Date of Issue: 12\31\98

Page 1 of 1

Project Name: Fort McClellan - CK05

Project Number: 774645

## -Variance Report -

I. Description: (by the person identifying the change)

FORMER MOTOR POOL 3100, PARCEL 146(7):

Temporary well FTA-146-GP02 was relocated approximately 30 feet north of direct-push soil boring location FTA-146-GP02.

Identified by: Jeffrey Tarr, PG - IT Site Manager

Date: 12-31-98

II. Justification For Variance:

The hollow-stem auger rig could not access the same location where the direct-push soil boring was completed. Therefore, temporary well FTA-146-GP02 was relocated approximately 30 feet from the direct-push soil boring location because of overhead power lines and buried underground utility lines.

III. Applicable Document/Work Plan: (by the person identifying the change)

Final Site-Specific Field Sampling Plan, Former Motor Pool 3100, Parcel 146(7), October 1998.

### Distribution List:

- . Jeanne Yacoub, IT Project Manager
- . Steve Moran, IT Technical Lead
- . Jeffrey Tarr, IT Site Manager
- . Randy McBride, IT QA Officer
- . Mr. Ellis Pope, US Army Corps of Engineers
- . Mr. Ross McCollum, US Army Corps of Engineers

### - Signatures -

Requested by: Jeffrey Tarr, PG - IT Site Manager 3/4/99 Date

Approved by: Jeanne Yacoub 4/1/99 3/8/99 Date

Project Manager Approval: Jeanne Yacoub 3/8/99 Date

QA Approval: Randy McBride 5-5-04 Date



Variance No: 1300OCTVAR

Linked w/NC No:

X

Date of Issue: 10/30/98

Page 1 of 1

Project Name: Fort McClellan - CK05

Project Number: 774645

## -Variance Report -

### I. Description: (by the person identifying the change)

MOTOR POOL 3100, 13<sup>TH</sup> AVENUE; PARCELS 146(7), 212(7), 24(7), 25(7), AND 73(7)

Direct-push temporary wells were not installed because groundwater was not encountered during drilling operations using direct-push technology. The following wells were not installed: FTA-146-GP02, FTA-146-GP05, FTA-146-GP06, FTA-146-GP07, FTA-146-GP08, FTA-146-GP09, and FTA-146-GP10.

Identified by: Jeffrey Tarr, PG - IT Site Manager

Date: 10-30-98

### II. Justification For Variance:

Unable to install direct-push temporary wells because groundwater was not encountered during drilling operations. Therefore, International Technology will attempt to install wells using a drill rig. Drilling using hollow-stem augers may produce enough groundwater so that wells can be developed and groundwater samples collected for laboratory analysis.

### III. Applicable Document/Work Plan: (by the person identifying the change)

Final Site-Specific Field Sampling Plan Motor Pool 3100, 13<sup>th</sup> Avenue, September 1998.

#### Distribution List:

1. Jeanne Yacoub, IT Project Manager
2. Steve Moran, IT Technical Lead
3. Jeffrey Tarr, IT Site Manager
4. Randy McBride, IT QA Officer
5. Mr. Ellis Pope, US Army Corps of Engineers
6. Mr. Ross McCollum, US Army Corps of Engineers

#### - Signatures -

Requested by: Jeffrey Tarr, PG - IT Site Manager 3/4/99 Date

Approved by: Ellis C. Pope 4/1/99 Date

Project Manager Approval: Jeanne Yacoub 3/4/99 Date

QA Approval: Randy McBride 5-5-04 Date